

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		•				•				
					-					
		•								
		u.			14.1	<u></u>				
Part No	:	PAR #:	Fault Category:	NCR: Yes	No DQ	A :	_ Date: _			

QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC	Corrective Action Section B			Verification	A	A ======t		
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
								•		
		y 12								
								-		

NOTE: Date & initial all entries

Each

: TUBÉ HANDLE

: PB6743001103

: B6743001 P.31

: 18/09/2008

: N/A

: B1

Monday, 18/08/2008 3:44:12 PM

User

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material **Due Date**

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 41364

Type

Estimate Number : 13445

P.O. Number

This Issue : 18/08/2008

Prsht Rev. : NC

: // First Issue

Previous Run

Comment

Written By

Checked & Approved By

: 41066

S.O. No. :

08-06-26 new issue DD verified by:ec

: SMALL/MED FAB

Additional Product

Job Number:



Seq. #:+

Machine Or Operation:

Description:

M6061T6T0500W125

6061-T6 RD Tube .500 x .125W

5.3416 f(s)

Comment: Qty.:

0.6677 f(s)/Unit Total: 6061-T6 RD Tube .500 x .125W

batch: m 108818.

SMALL FAB 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1- cut to length as per dwg

2- make a 0.063" chamfer on both ends of tube

3- deburr

3.0

QC5



Comment: INSPECT WORK TO CURRENT STEP

PACKAGING ' 4.0


PACKAGING RESOURCE #1




Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:





5.0

QC21

INAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-10-16